


Sunbeam®




**Instructions for
70 oz./2000 g. Precision
Electronic Digital Scale**

Model 78411-04

AC ADAPTER OPERATION

(not included)



54004
ADPT 15

To connect AC adapter:

1. Plug the tip of the AC adapter into the receptacle on back of the scale base housing. The scale may be powered by the Sunbeam model 78803-02 adapter, and can be left plugged in when not in use.
2. Your scale is ready to be used.

Note: Always insert the adapter tip into scale before plugging adapter into electrical outlet. Also, disconnect from outlet before pulling tip of adapter from back of scale.

HOW TO USE YOUR PRECISION SCALE

1. Place scale on a hard flat surface.
2. Select OZ/GM by sliding switch under top tray on right rear side to desired measurements.
3. Press the ON-RESET-GROSS switch pad, the display will show "0.0" (oz/g).
4. Place item to be weighed in the center of the platform.
5. The weight of the item being weighed will be displayed.
6. Caution should be taken not to exceed the total capacity of the scale (70 oz. or 2000 g). Exceeding this amount could damage scale and will **void warranty**.

HOW TO USE THE MULTIPLE TARE AND GROSS WEIGHT FEATURE

1. After weighing the first item, press ON-RESET-GROSS switch pad and scale will automatically reset to zero. Display will show a small triangle ▲ in the upper left hand corner.
2. Place next item to be weighed onto scale. Scale will give weight of second item only.
3. Press the ON/RESET-GROSS switch pad again to get the gross weight of both items combined. Repeat steps 2 and 3 for additional items.
4. Caution should be taken not to exceed the total capacity of the scale (70 oz. or 2000 g). Exceeding this amount could damage scale and will **void warranty**.

WEAK BATTERY INDICATOR

If the battery is weak or needing replaced, the display will show (LO). When this occurs the battery must be replaced with a new 9 volt alkaline battery. If the scale will not be used for an extended period, it is recommended that the battery be removed.

POSTAL RATE FEATURE

Included with the scale is a Postal Rate Chart for computing postage. To use, weigh the letter or package in the manner described previously. After weight has been determined, refer to the corresponding weight category on rate chart to determine the postage amount.

CALORIE COUNTER FEATURE

Enclosed with scale is a calorie chart. To use, weigh the food and multiply by the corresponding calorie value for that item to determine the calorie total.

CUSTOMER SERVICE HELP LINE

We want to be sure you are completely satisfied with your new purchase. If you have any questions or experience any problems please call our help line, Sunbeam Consumer Affairs (in the United States), at 1-800-597-5978 between 8:00-5:00 CST - Monday through Friday. In Canada, call 1-800-66-SUNBEAM.

FULL ONE YEAR WARRANTY

Sunbeam-Oster Household Products warrants this product to be free from defects in materials and workmanship for a period of one year from the date of original retail purchase. If the product fails during the warranty period, return it postage-prepaid with a short description of the problem and proof of purchase to one of the following addresses (depending on place of purchase) for repair or replacement at our option. Please do not return this product to the place of purchase; doing so may delay the processing of your claim and the repair of your product. If we cannot repair the defects, you may elect to receive a replacement or refund. This warranty gives you specific legal rights, and you may also have other rights which vary from state to state.

**In the U.S., please send to: Sunbeam Service Station, 160 Commerce Drive,
P.O. Box 508, Bay Springs, MS 39422.**

**In Canada, please send to: Sunbeam Service Station, 5975 Falbourne St.,
Mississauga, Ontario L5R 3V8**

**In Mexico, please send to: Sunbeam Mexicana S.A. DE C.V., via Dr. Gustavo Baz P.
No. 180, Tlalnepantla, Edo. de Mexico, C.P. 54090**

This warranty gives you specific legal rights, and you may have other rights which vary from state to state or province to province.

SAVE THESE INSTRUCTIONS

P.N. 66335